From: Lee, Purcell N

Sent: Tuesday, March 17, 2009 1:35 PM

To: Wagganer, Kevin L; Bentel, John A; Scott, Andrew C

Cc: Duncan, Bruce E

Subject:Secretary Residential Installation HotwashAttachments:Secretary Residential Installation Hotwash.docx

RELEASE IN PART D6

REVIEW AUTHORITY: Archie Bolster, Senior Reviewer

Attached is the agenda/talking points for the hot wash.

Secretary Residential Installation Hotwash

RELEASE IN FULL

REVIEW AUTHORITY: Archie

Bolster, Senior Reviewer

1. Equipment location:

a. Unclassified Partner System:

i. Server: Basement Telephone Closet

ii. Telephone Set: Various rooms

b. Classified Fax:

i. STE/Secure Fax: Third Floor

c. Classified Red Switch: Third Floor

2. Status of Installation:

a. Unclassified Partner Telephone System: Completed.

b. Classified STE/Fax: Completed

c. Classified Red Switch: Completed

d. Unclassified Ops Drop: Verizon is still working to finalize path.

e. CMS Classified Video: Declined

f. CMS Classified Voice: Declined

3. Issues:

- a. T1 Telephone Services were not available upon arrival
- b. Analog lines (2) for the Partner system was not ordered.
- c. Red Switch Technicians arrived 2 days later than scheduled.
- d. SDS Data Cable was left in Washington
- e. Former President's wireless headset was disconnected
- f. Secretary Clinton's headset noise cancelling was not selected
- g. Speed Dial for Secretary Clinton Unclassified telephone was not working properly.
- h. Secretary's Clinton's business lines were not set up in a "Hunt Group"